



## OHIO HISTORIC INVENTORY

RPR Number:


1. No. <b>LOR-02266-21</b>		4. Present Name(s) <b>Doyle and Gail Jones House</b>		LOR-02266 6-21
2. County <b>Lorain</b>		5. Historic or Other Name(s)		
6. Specific Address or Location <b>450 South Main</b>		19a. Design Sources	35. Plan Shape <b>Irregular</b>	Lorain 2. County
6a. Lot, Section or VMD Number <b>0900105000002</b>		20. Contractor or Builder	36. Changes associated with 17/17b Dates: 17. <b>Original/Most significant construct</b>	
7. City or Village <b>Oberlin</b>		21. Building Type or Plan <b>Side Hallway</b>	17b. <b>Some alteration</b>	Doyle and Gail Jones House 4. Present or Historic Name(s)
9. U.T.M. Reference Quadrangle Name: <b>Oberlin</b> <b>17 397986 4570482</b> Zone Easting Northing		22. Original Use, if apparent <b>UNKNOWN USE</b>	37. Window Type(s) <b>6 over 6</b>	
10. Classification: <b>Building</b>		23. Present Use <b>Single Dwelling</b>	38. Building Dimensions <b>42' x 25'</b>	
11. On National Register? <b>NO</b>		24. Ownership <b>Private</b>	39. Endangered? <b>NO</b> By What?	
13. Part of Established Hist. Dist? <b>NO</b>		25. Owner's Name & Address, if known <b>Doyle J. &amp; Gail A. Jones</b> <b>450 S. Main St.</b> <b>Oberlin, OH, 44074</b>	40. Chimney Placement <b>Off center within roof surface</b>	
15. Other Designation (NR or Local)		26. Property Acreage <b>3.2</b>	41. Distance from & Frontage on Road <b>50'</b>	
16. Thematic Associations: <b>Residential</b> <b>AGRICULTURE</b>		27. Other Surveys	51. Condition of Property: <b>Good/Fair</b>	
17. Date(s) or Period <b>ca. 1865-1885</b>		28. No. of Stories <b>Two story</b>	52. Historic Outbuildings & Dependencies Structure Type <b>Garage</b>	
17b. Alteration Date(s) <b>unknown</b>		29. Basement? <b>Yes</b>	Date <b>modern</b>	
18. Style Class and Design <b>No academic style - Vernacular</b> Element <b>Colonial Revival</b>		30. Foundation Material <b>Poured concrete</b>	Associated Activity <b>Original/Most significant construction</b>	
18a. Style of Addition or Elements(s) Element <b>Greek Revival</b>		31. Wall Construction <b>Balloon/western/platform frame</b>	53. Affiliated Inventory Numbers Historic (OHI) Archaeological (OAI)	
19. Architect or Engineer		32. Roof Type <b>Gable</b> Roof Material <b>Asphalt shingle</b>		
		33. No. of Bays <b>7</b> Side Bays		
		34. Exterior Wall Material(s) <b>Wood shingle</b>		
42. <i>Further Description of Important Interior and Exterior Features (Continued on Reverse if Necessary)</i> <p>This side hallway house appears to have once been Greek Revival, but has undergone several changes, making it appear to be a Colonial Revival house. The original body of the house is centered at the front (east) elevation, and has added wings to its left and right. At the original body of the house, the door is at the left side and is flanked by pilasters, with an entablature above, giving the house its (likely original) Greek Revival appearance. Cement steps lead up to the wood door, which has sidelights, as well as a wood and glass storm door. To the right of the entry, a projecting bay has cutaway sides. The three windows in the bay are 9/9 and have pediments above them, with filled panels below. The second story has three 6/6 windows with shutters, and a vent is in the attic. The left wing, which is one story, has two 6/6 windows with shutters. At the right wing, the porch is enclosed. At the enclosed portion, a wood, shingled wall runs around the perimeter, with six screened-in, 1/1 windows above. Square posts sit at the corners of the porch. The north elevation has a single, 6/6 window at the first story of the wing, with a vent in the gable, flanked by continued...</p>				
43. <i>History and Significance (Continue on Reverse if necessary)</i> <p>This farmhouse is located just south of Hamilton Street, which was the town limit for many years. This makes it difficult to track residents in city records and telephone directories. Doyle. J. Jones and his wife Gail A. are the first known occupants of this home, according to city directory research, since 1971. Based on deed transfers and a vague address listing, it is possible that Andrew R. and Clara Johnston lived at this property prior to the Jones family. Doyle and Gail Jones are still currently the owners of this residence.</p>				
44. <i>Description of Environment and Outbuildings (See #52)</i> <p>Picket fence surrounds the rear yard. The garage is detached; it is modern, and has two car doors, as well as a pedestrian door to the right of the car doors. A 6/6 window is located to the right of the pedestrian door. A large historic English or Three Bay barn used to be situated on this property and was recently demolished. The barn was wood with asbestos shingles in its side gable roof. A third outbuilding is small, with side gables and historic windows. This building may have functioned as continued...</p>				
45. <i>Sources of Information</i> <p>O-High Alumni, Internet, <a href="http://www.oberlin-high.org">http://www.oberlin-high.org</a>, Accessed December 2010; City Directories, Oberlin Heritage Center Resource Center; Holsworth, Pat. Oberlin Pioneer Database; Sanborn Fire Insurance Maps; Gordon, Stephen C. 'How to Complete the Ohio Historic Inventory.' Columbus: Ohio Historical Society, 1992; McAlester, Virginia and Lee. 'A Field Guide to American Houses.' New York: Alfred K. Knopf Inc., 2000; 'Alumni Register: Graduates and Former Students, Teaching and Administrative continued...</p>				
46. Prepared By: <b>Liz Schultz</b>		47. Organization: <b>Oberlin Heritage Center</b>		48. Date Recorded: <b>12/31/2010</b>
49. PIR Reviewer:				50. PIR Review Date:

LOR-02266  
6-21Lorain  
2. CountyDoyle and Gail Jones House  
4. Present or Historic Name(s)450 South Main  
6. Specific Address or Location

1. No. <b>LOR-02266-21</b>	4. Present Name(s) <b>Doyle and Gail Jones House</b>
2. County <b>Lorain</b>	5. Historic or Other Name(s)

8. Site Plan with North Arrow

54. Farmstead Plan :



Door Selection:  
**Single off center**

Door Position:  
**Flush**

Orientation:  
**Gable dominant with multiple smaller lateral extension**

Symmetry:  
**Bilateral symmetry**

Report Associated With Project:

NADB #:



1. No. <b>LOR-02266-21</b>	4. Present Name(s) <b>Doyle and Gail Jones House</b>
2. County <b>Lorain</b>	5. Historic or Other Name(s)

42. *Further Description of Important Interior and Exterior Features (Con't)*

**sidelights. At the original portion of the house, the far left and right sides of the second story have 6/6 windows. A pair of windows with six lights is at the right corner of the main body of the house. The first addition is one story and has an 8/8 window with shutters, as well as an exterior chimney that faces west. The rear addition has no windows. The south elevation is obscured, but at the right, the gabled one-story wing has a 6/6 window with shutters. To the left, the house extends out towards the rear and has a recessed porch with a wood balustrade and wood railing along the steps. There are windows within the porch. Three large windows are left of the porch, and at the far left, a door appears to be a modern door.**

43. *History and Significance (Con't)*

44. *Description of Environment and Outbuildings (Con't)*

**a summer kitchen, root cellar, or other purpose. This house is located on a corner of South Main Street, a busy thoroughfare in Oberlin, as the street changes from a residential landscape to a rural landscape.**

45. *Sources (Con't)*

**Staff, (1833-1960).' Oberlin: Oberlin College, 1961; Lorain County Auditor Property Record, Internet, <http://www.loraincounty.com/auditor/index.shtml>, Accessed December 2010.**