



# OHIO HISTORIC INVENTORY



RPR Number:

1. No. <b>LOR-02147-21</b>		4. Present Name(s) <b>Geneva Jones House</b>		LOR-0214 7-21
2. County <b>Lorain</b>		5. Historic or Other Name(s) <b>Jones House</b>		
6. Specific Address or Location <b>98 East Vine</b>		19a. Design Sources		Lorain
6a. Lot, Section or VMD Number <b>0900086106025</b>		20. Contractor or Builder		
7. City or Village <b>Oberlin</b>		21. Building Type or Plan <b>Ranch</b>		2. County
9. U.T.M. Reference Quadrangle Name: <b>Oberlin</b> <b>17 398352 4571555</b> Zone Easting Northing		22. Original Use, if apparent <b>Single Dwelling</b>		
10. Classification: <b>Building</b>		23. Present Use <b>Single Dwelling</b>		4. Present or Historic Name(s)
11. On National Register? <b>NO</b>		24. Ownership <b>Private</b>		
13. Part of Established Hist. Dist? <b>NO</b>		25. Owner's Name & Address, if known <b>Geneva Jones</b> <b>98 E. Vine St.</b> <b>Oberlin, OH, 44074</b>		Geneva Jones House
15. Other Designation (NR or Local)		26. Property Acreage <b>0.27</b>		
16. Thematic Associations: <b>Residential</b>		27. Other Surveys		98 East Vine
17. Date(s) or Period <b>1961</b>		28. No. of Stories <b>One story</b>		
18. Style Class and Design <b>No academic style - Vernacular</b>		29. Basement? <b>Unknown</b>		6. Specific Address or Location
18a. Style of Addition or Element(s)		30. Foundation Material <b>Concrete block</b>		
19. Architect or Engineer		31. Wall Construction <b>Balloon/western/platform frame</b>		98 East Vine
		32. Roof Type <b>Gable</b> Roof Material <b>Asphalt shingle</b>		
		33. No. of Bays <b>3</b> Side Bays <b>3</b>		98 East Vine
		34. Exterior Wall Material(s) <b>Aluminum or vinyl siding</b>		
35. Plan Shape <b>Square</b>				
36. Changes associated with 17/17b Dates: 17. <b>Original/Most significant construct</b> 17b.				
37. Window Type(s) <b>1 over 1</b>				
38. Building Dimensions <b>38' x 42'</b>				
39. Endangered? <b>NO</b> By What?				
40. Chimney Placement <b>Off center within ridaeline</b>				
41. Distance from & Frontage on Road <b>25'</b>				
42. Further Description of Important Interior and Exterior Features (Continued on Reverse if Necessary) <b>This one-story ranch house has three bays at the facade and a side gable asphalt roof. The foundation appears to be made of concrete block. At the facade (south elevation), the entry is situated slightly left of center and appears to be original. The door has decorative square overlays, with circles adorning the center of each square; the top square is a window. Three poured concrete block steps lead up to the stoop in front of the door. A window element at the left consists of a larger central window flanked by 1/1 double hung windows. To the right, a pair of 2/2 windows are slightly shorter than the windows in the element to the left. Shutters on these front windows consist of three vertical boards, spaced slightly apart. The west elevation is comprised of the original gabled portion, and a likely lateral addition. In the original section of the house, two 2/2 windows are left of center and a triangular vent is in the gable. In the lateral portion, at the right, a window element with shutters matches the element on the facade (a center, fixed window, flanked by 1/1 windows). Another window is located to the far left in the lateral portion. The east elevation continued...</b>				
43. History and Significance (Continue on Reverse if necessary) <b>According to the Lorain County Auditor this house was built in 1961. The first known residents listed in the 1970 city directory were Roy and Geneva Jones. Roy was listed as a foundry worker. In subsequent years only Geneva was listed in telephone books, and as of 2010 Geneva Jones is still the current owner and resident. Geneva (nee Denny) graduated from Oberlin High School in 1946. In 1999 Jason Brown was also a resident, and since 2005 B. Randleman has also been a resident, along with Jones.</b>				
44. Description of Environment and Outbuildings (See #52) <b>No outbuildings are visible for this house, which is surrounded by manicured shrubbery. The small yard contains several small trees. The driveway is cement. The house is located on a primarily residential street. To the east and west of the house are other residences. Across the street is a large apartment building.</b>				
45. Sources of Information <b>O-High Alumni, Internet, http://www.oberlin-high.org, Accessed December 2010; City Directories, Oberlin Heritage Center Resource Center; Holsworth, Pat. Oberlin Pioneer Database; Sanborn Fire Insurance Maps; Gordon, Stephen C. 'How to Complete the Ohio Historic Inventory.' Columbus: Ohio Historical Society, 1992; McAlester, Virginia and Lee. 'A Field Guide to American Houses.' New York: Alfred K. Knopf Inc., 2000; 'Alumni Register: Graduates and Former Students, Teaching and Administrative continued...</b>				
46. Prepared By: <b>Liz Schultz</b>		47. Organization: <b>Oberlin Heritage Center</b>		48. Date Recorded: <b>12/31/2010</b> 50. PIR Review Date:
49. PIR Reviewer:				

1. No. <b>LOR-02147-21</b>	4. Present Name(s) <b>Geneva Jones House</b>
2. County <b>Lorain</b>	5. Historic or Other Name(s) <b>Jones House</b>

8. Site Plan with North Arrow

54. Farmstead Plan :



Door Selection:  
**Single centered**

Door Position:  
**Flush**

Orientation:  
**Lateral axis**

Symmetry:  
**Bilateral asymmetry**

Report Associated With Project:

NADB #:



1. No. <b>LOR-02147-21</b>	4. Present Name(s) <b>Geneva Jones House</b>
2. County <b>Lorain</b>	5. Historic or Other Name(s) <b>Jones House</b>

42. *Further Description of Important Interior and Exterior Features (Con't)*

mainly has the gabled, original portion visible. This gabled portion contains a door to the far left, which has a large window in its upper half; the window is divided by a single, horizontal muntin. At the center of the east elevation is a small 2/2 window, and another slightly larger 2/2 window is at the right. A triangular vent is in the gable. At the rear of the house is a wood deck. The rear addition is set back along the deck and is barely visible from the road.

43. *History and Significance (Con't)*

44. *Description of Environment and Outbuildings (Con't)*

45. *Sources (Con't)*

Staff, (1833-1960). 'Oberlin: Oberlin College, 1961; Lorain County Auditor Property Record, Internet, <http://www.loraincounty.com/auditor/index.shtml>, Accessed December 2010.