

51. Condition of Property

<input type="checkbox"/> Excellent	<input type="checkbox"/> Ruin
<input checked="" type="checkbox"/> Good/Fair	<input type="checkbox"/> Destroyed/Burned
<input type="checkbox"/> Deteriorated	Date _____

54. Farmstead Plan



52. Historic Outbuildings and Dependencies

Barn Type(s)

<input type="checkbox"/> Corn Crib or Shed	<input type="checkbox"/> Summer Kitchen	<input type="checkbox"/> Silo
<input type="checkbox"/> Smoke House	<input type="checkbox"/> Spring House	<input type="checkbox"/> Ice House
<input type="checkbox"/> Designed Landscape Features	<input type="checkbox"/> Privy	<input type="checkbox"/> Garage

53. Affiliated OAI Site Number(s) _____

OAI Completed? _____

Archaeological Feature:	Observed	Expected on Basis of Archival Research
Well	<u>No</u>	<u>No</u>
Privy	<u>No</u>	<u>No</u>
Cistern	<u>No</u>	<u>No</u>
Foundation	<u>No</u>	<u>No</u>
Structural Rubble	<u>No</u>	<u>No</u>
Formal Trash Dump	<u>No</u>	<u>No</u>
Other _____	<u>No</u>	<u>No</u>

42. Further Description of Important Interior and Exterior Features (Continued from page 1)

43. History and Significance (Continued from page 1.)

the now demolished building to the north. The two buildings were connected by a second floor enclosed bridge. In 1925, Mr. Hobbs sold the building to John Gardner (Maddock files). The rear section of the building has been recently divided to provide space for H & R Block on the south face.