



# OHIO HISTORIC INVENTORY

Ohio Historic Preservation Office  
567 E. Hudson St. Columbus, Ohio 43211  
614/297-2470



1. No.	2. County LOR	4. Present Name(s)		<input type="checkbox"/> Coded
3. Location of Negatives O.H.I.O. Resource Roll # Exp. # Facing 2		5. Historic or Other Name(s) Judson Cottage		
6. Specific Address or Location 108 East College Street		17. Date(s) or Period c.1890	17b. Alteration Date(s)	30. Foundation Material Sandstone
6a. Lot, Section or VMD Number		18. Style or Design Shingle Style	High Style <input type="checkbox"/> Elements <input checked="" type="checkbox"/>	31. Wall Construction Wood frame
7. City or Village If Ru ship & Vicinity Oberlin		18a. Style of Addition or Element(s)		32. Roof: Type Gable w/ Cross Gable Pitch Moderate Material Asphalt Shingle
8. Site Plan with North Arrow 		19. Architect or Engineer unknown		33. No. Bays Front 4 Side 6
9. U.T.M. Reference Quadrangle Name Zone Easting Northing <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		19a. Design Sources unknown		34. Exterior Wall Material(s) Vinyl Siding Wood, Undulated Wood Shingle
10. <input type="checkbox"/> Site <input type="checkbox"/> Structure <input checked="" type="checkbox"/> Building <input type="checkbox"/> Object		20. Contractor or Builder unknown		35. Plan Shape Irregular
11. On National Register ? No		21. Building Type or Plan Other House		36. Changes (Explain in #42) Unknown
12. N.R. Potential ? Yes		22. Original Use, if apparent Multiple Dwelling		37. Window Type(s) 6 over 1
13. Part of Estb Hist Dist? No		23. Present Use Multiple Dwelling, Apartment House		38. Bldg. Dims. 80' x 60' approx.
14. Dist. Potential ? Yes		24. Ownership <input type="checkbox"/> Public <input checked="" type="checkbox"/> Private		39. Endangered? No Explain:
15. Name of Established District (N.R. or Local)		25. Owner's Name & Address, if known		40. Chimney Placement Lateral Exterior
16. Thematic Association(s) College, Religious		26. Property Acreage		41a. Distance from road 200' approx.
42. Further Description of Important Interior and Exterior Features This large house has a protrusion on the second floor which creates the roof of the small porch below. This is situated slightly right of the center of the building. The porch has a square spindle railing and square columns. There are two large exterior chimneys on the front of the house, and the symmetry of their placement accentuates how off-center the porch and entryway are. There are other entrances on the east side of the house to the different apartments. The first story of the house has horizontal vinyl siding, but the second story has wood shingle siding, separated by a flared beltcourse.		27. Other Surveys in Which Included no		41b. Frontage on road 60' approx.
43. History and Significance Owned by Sarah Cowles Little in 1894, the house was named Judson Cottage. It was used to house missionaries who had returned home as ministers with their children, most of whom attended Oberlin College. It passed through many ministers' hands, and eventually was divided into three apartments and used primarily by students at Oberlin College. This house and Dickenson Cottage which sits next to it are both tied to Tank Hall because of their missionary associations.		28. No. of Stories 2		
44. Description of Environment and Outbuildings (see #52) This house sits behind Tank Hall, and is barely visible from the road.		29. Basement? yes		
45. Sources of Information Lorain County Courthouse, Auditor Property Records, 2001. Internet. <a href="http://www.loraincounty.com/auditor/index.shtml">http://www.loraincounty.com/auditor/index.shtml</a> . Oberlin Historic Preservation Commission Files. O.H.I.O. Resource Center Files. Oberlin City Directories.		46. Prepared by D.G. Henry, G. Baudoin, M. Franck		47. Organization O.H.I.O. and H.P.C.
		48. Date Recorded 1/16/2002		49. Revised by
		50a. Date Revised		50b. Reviewed by

Barn Type(s)

n/a

---

42. Further Description of Important Interior and Exterior Features (Continued from page 1)

43. History and Significance (Continued from page 1.)