

# OHIO HISTORIC INVENTORY

Ohio Historic Preservation Office  
567 E. Hudson St. Columbus, Ohio 43211  
614/297-2470



1. No.	2. County LOR	4. Present Name(s)		<input type="checkbox"/> Coded
3. Location of Negatives O.H.I.O. Resource		5. Historic or Other Name(s) E. H. Holter House, J.D. Mosher House, Mack House, Michaelides-Langner House		
Roll #	Exp. # Facing			
Front	2 05			
6. Specific Address or Location 168 East College Street		17. Date(s) or Period c. 1885	17b. Alteration Date(s)	30. Foundation Material Sandstone
6a. Lot, Section or VMD Number 0900086109043		18. Style or Design Queen Anne	High Style <input type="checkbox"/>	31. Wall Construction Wood Frame
7. City or Village If Rural, Township & Vicinity Oberlin		18a. Style of Addition or Element(s)	Elements <input checked="" type="checkbox"/>	32. Roof: Type Hip and Gable Pitch Steep Material Slate, Patterned
8. Site Plan with North Arrow		19. Architect or Engineer unknown	33. No. Bays Front 5 Side 3	
		19a. Design Sources unknown		
		20. Contractor or Builder unknown	34. Exterior Wall Material(s) Wood, Horizontal Siding	
9. U.T.M. Reference Quadrangle Name		21. Building Type or Plan Other House	35. Plan Shape L-Shaped	
Zone	Easting	22. Original Use, if apparent Single Dwelling	36. Changes (Explain in #42) Altered	
<input type="checkbox"/>	<input type="checkbox"/>	23. Present Use Single Dwelling	37. Window Type(s) 1 over 1	
10. <input type="checkbox"/> Site <input type="checkbox"/> Structure		24. Ownership <input type="checkbox"/> Public <input checked="" type="checkbox"/> Private	38. Bldg. Dims. 40' x 67'	
<input checked="" type="checkbox"/> Building <input type="checkbox"/> Object		25. Owner's Name & Address, if known	39. Endangered? No Explain:	
11. On National Register ? No	12. N.R. Potential ? No	26. Property Acreage .3	40. Chimney Placement Two, Off Center Within Roof Surface	
13. Part of Estb Hist Dist? No	14. Dist. Potential ? Yes	27. Other Surveys in Which Included no	41a. Distance from road 35' approx.	
15. Name of Established District (N.R. or Local)		28. No. of Stories 2 and 1/2	41b. Frontage on road 69'	
16. Thematic Association(s) College, Business		29. Basement? Partial		
42. Further Description of Important Interior and Exterior Features The home features some elements of the Queen Anne Style. The front porch projects only slightly from the house and has square columns supported a low-pitched asphalt shingle roof. The roof line is broken by many gables, which have diagonal wooden siding on them. The slate roof tile pattern is unique, switching back and forth between imbricated and fishscale. The front door is centered, though recessed in the porch. The home has brackets. A few of the windows in the house have stained glass. On the west side of the house, there is one gable and one large bay window. On the east side of the house is another large bay window.				
43. History and Significance This house was built prior to 1886, and the earliest known resident was Ernest H. Holter, who lived there until about 1916. He made his living as a jeweler in Oberlin. He resided there with his wife Mary Barry, and a relative, Fred Master Holter. After Holter, an English professor named Jesse Mack and his wife Pearl lived there until about 1942. G.P. Michaelides and his wife Donna lived in the residence in the late 1950's and early 1960's. He was an interim division director and lecturer at the college. The house suffered a chimney fire in 1981.		46. Prepared by D. G. Henry, G. Baudoin, M. Franck		
44. Description of Environment and Outbuildings (see #52) This house shares a paved driveway with its neighbor to the west. Behind the house is a detached garage and woodshed which was built in 1984. A walkway leads from the sidewalk to the front porch.		47. Organization O.H.I.O. and H.P.C.		
45. Sources of Information Lorain County Courthouse, Auditor Property Records, 2001. Internet. <a href="http://www.loraincounty.com/auditor/index.shtml">http://www.loraincounty.com/auditor/index.shtml</a> . Oberlin Historic Preservation Commission Files. O.H.I.O. Resource Center Files. Oberlin City Directories. Fire insurance maps.		48. Date Recorded 1/16/2002		
		49. Revised by		
		50a. Date Revised		
		50b. Reviewed by		

51. Condition of Property

<input type="checkbox"/> Excellent	<input type="checkbox"/> Ruin
<input checked="" type="checkbox"/> Good/Fair	<input type="checkbox"/> Destroyed/Burned
<input type="checkbox"/> Deteriorated	Date _____

54. Farmstead Plan



52. Historic Outbuildings and Dependencies

Barn Type(s)

n/a

<input type="checkbox"/> Corn Crib or Shed	<input type="checkbox"/> Summer Kitchen	<input type="checkbox"/> Silo
<input type="checkbox"/> Smoke House	<input type="checkbox"/> Spring House	<input type="checkbox"/> Ice House
<input type="checkbox"/> Designed Landscape Features	<input type="checkbox"/> Privy	<input type="checkbox"/> Garage

53. Affiliated OAI Site Number(s) \_\_\_\_\_

OAI Completed? \_\_\_\_\_

Archaeological Feature:	Observed	Expected on Basis of Archival Research
Well	<u>No</u> _____	<u>No</u> _____
Privy	<u>No</u> _____	<u>No</u> _____
Cistern	<u>No</u> _____	<u>No</u> _____
Foundation	<u>No</u> _____	<u>No</u> _____
Structural Rubble	<u>No</u> _____	<u>No</u> _____
Formal Trash Dump	<u>No</u> _____	<u>No</u> _____
Other _____	<u>No</u> _____	<u>No</u> _____

42. Further Description of Important Interior and Exterior Features (Continued from page 1)

43. History and Significance (Continued from page 1.)