



OHIO HISTORIC INVENTORY

RPR Number:


Form with multiple sections: 1. No. LOR-02092-21, 4. Present Name(s) Zgrabik House, 6. Specific Address or Location 360 North Main, 19a. Design Sources, 35. Plan Shape Latin cross, 42. Further Description of Important Interior and Exterior Features, 43. History and Significance, 44. Description of Environment and Outbuildings, 45. Sources of Information.

LOR-0209
2-21
Lorain
2. County
Zgrabik House
4. Present or Historic Name(s)
360 North Main
6. Specific Address or Location

1. No. LOR-02092-21	4. Present Name(s) Zgrabik House
2. County Lorain	5. Historic or Other Name(s) Zgrabik House

8. Site Plan with North Arrow

54. Farmstead Plan :



Door Selection:
Two doors symmetrical

Door Position:
Flush

Orientation:
Gable dominant with multiple smaller lateral extension

Symmetry:
Bilateral symmetry

Report Associated With Project:

NADB #:



1. No. LOR-02092-21	4. Present Name(s) Zgrabik House
2. County Lorain	5. Historic or Other Name(s) Zgrabik House

42. Further Description of Important Interior and Exterior Features (Con't)

center, which has two 1/1 windows at the first story, with arched pediments, and a pair of 1/1 windows in the second story, which sit under a continuous arch, as in the east elevation. At the right side, the porch shades a 1/1 window with an arch at the first story. The second story also has a 1/1 with an arch. At the far left, a two story addition, which is shorter than the original body of the house, is obscured, but several windows are visible. The north elevation has a gabled portion at the center, with the same window arrangement as the east and south elevations. To their left, at the first story, a pair of square windows has an entablature. At the second story, above the porch, a 1/1 has an arched pediment. To the right of the gable, another porch is visible, which has a wood balustrade below the roof's eaves, and an altered metal railing and metal supports. The porch shades three windows (though the center window has been filled with a panel of wood) at the first story. Above the porch, a 1/1 window is set in the second story.

43. History and Significance (Con't)

side of Route 1. John and Cecilia are listed as living on the east side of RD 1 in 1956, and then on the west side in 1961. They had one child. John was a mechanic, at one time at Murphy's Garage, and died in 1998. As of 2010 the owners are listed as Robert J. and Cecilia C. Zgrabik, trustees.

44. Description of Environment and Outbuildings (Con't)

45. Sources (Con't)

Staff, (1833-1960).¹ Oberlin: Oberlin College, 1961; Lorain County Auditor Property Record, Internet, <http://www.loraincounty.com/auditor/index.shtml>, Accessed December 2010.