

OHIO HISTORIC INVENTORY

Ohio Historic Preservation Office
567 E. Hudson St. Columbus, Ohio 43211
614/297-2470



1. No.	2. County LOR	4. Present Name(s) Ginko Gallery		<input type="checkbox"/> Coded									
3. Location of Negatives O.H.I.O. Resource		5. Historic or Other Name(s) Standard Drug; Moore Drug; Miranda Used Books											
<table border="1" style="width:100%; border-collapse: collapse;"> <tr> <th>Roll #</th> <th>Exp. #</th> <th>Facing</th> </tr> <tr> <td>Front 1</td> <td>11</td> <td>E</td> </tr> <tr> <td>Rear 2</td> <td>15</td> <td>W</td> </tr> </table>		Roll #	Exp. #	Facing	Front 1	11	E	Rear 2	15	W			
Roll #	Exp. #	Facing											
Front 1	11	E											
Rear 2	15	W											
6. Specific Address or Location 19 South Main Street		17. Date(s) or Period 1939	17b. Alteration Date(s)	30. Foundation Material Concrete									
6a. Lot, Section or VMD Number 09-00-086-102-007		18. Style or Design No academic style - vernacular	High Style <input type="checkbox"/>	31. Wall Construction Masonry									
7. City or Village Oberlin		18a. Style of Addition or Element(s) Period Revival	Elements <input checked="" type="checkbox"/>	32. Roof: Type Slate Pitch Steep Material Slate									
8. Site Plan with North Arrow		19. Architect or Engineer		33. No. Bays Front 3 Side									
		19a. Design Sources		34. Exterior Wall Material(s) Wood Siding									
9. U.T.M. Reference		20. Contractor or Builder		35. Plan Shape Rectangular									
<table border="1" style="width:100%; border-collapse: collapse;"> <tr> <th>Zone</th> <th>Easting</th> <th>Northing</th> </tr> <tr> <td><input type="checkbox"/></td> <td><input type="checkbox"/></td> <td><input type="checkbox"/></td> </tr> </table>		Zone	Easting	Northing	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	21. Building Type or Plan Other		36. Changes (Explain in #42)			
Zone	Easting	Northing											
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>											
10. <input checked="" type="checkbox"/> Building		22. Original Use, if apparent Commercial, Retail		37. Window Type(s) Other									
11. On National Register? no		23. Present Use Commercial, Retail		38. Bldg. Dims. 26 ft. X 102 ft.									
12. N.R. Potential? no		24. Ownership <input type="checkbox"/> Public <input checked="" type="checkbox"/> Private		39. Endangered? no Explain:									
13. Part of Estb Hist Dist? no		25. Owner's Name & Address, if known		40. Chimney Placement No Chimney Observed									
14. Dist. Potential? yes		26. Property Acreage .061		41a. Distance from road 12.5 ft.									
15. Name of Established District (N.R. or Local)		27. Other Surveys in Which Included Dobson-Brown		41b. Frontage on road 26 ft.									
16. Thematic Association(s) Commerce		28. No. of Stories 1											
42. Further Description of Important Interior and Exterior Features A one story commercial building with a colored slate tile roof and a central roof dormer. Central recessed entryway has simple fluted pilasters and is flanked by two large glass storefront windows. A large sign extends along the entire facade above the door and windows.		29. Basement? Yes											
43. History and Significance In 1939 George Bailey purchased two small buildings on the site, demolished them, and erected the current structure. Businesses have included a drug store, a gift shop, a used book store, today it is an artist studio and sales gallery. The first buildings on the site were built prior to 1855 and were destroyed in the fire of 1871. The next building on the site was completed by 1889. All buildings at this location have been single story structures. Until 1939 there was an alley on the north side of this lot. The builders daughter, (cont.)													
44. Description of Environment and Outbuildings (see #52) This structure is centrally located in the South Main Street commercial district.													
45. Sources of Information Fred Maddock files. at O.H.I.O. Resource Center and Oberlin College Archives; Oberlin H.P.C. files; Lorain County Courthouse tax records.				46. Prepared by									
				47. Organization O.H.I.O. and H.P.C.									
				48. Date Recorded 12/8/1998									
				49. Revised by									
				50a. Date Revised									
				50b. Reviewed by									

51. Condition of Property

<input type="checkbox"/> Excellent	<input type="checkbox"/> Ruin
<input checked="" type="checkbox"/> Good/Fair	<input type="checkbox"/> Destroyed/Burned
<input type="checkbox"/> Deteriorated	Date _____

54. Farmstead Plan



52. Historic Outbuildings and Dependencies

Barn Type(s)

<input type="checkbox"/> Corn Crib or Shed	<input type="checkbox"/> Summer Kitchen	<input type="checkbox"/> Silo
<input type="checkbox"/> Smoke House	<input type="checkbox"/> Spring House	<input type="checkbox"/> Ice House
<input type="checkbox"/> Designed Landscape Features	<input type="checkbox"/> Privy	<input type="checkbox"/> Garage

53. Affiliated OAI Site Number(s) _____

OAI Completed? _____

Archaeological Feature:	Observed	Expected on Basis of Archival Research
Well	no _____	no _____
Privy	no _____	no _____
Cistern	no _____	no _____
Foundation	no _____	no _____
Structural Rubble	no _____	no _____
Formal Trash Dump	no _____	no _____
Other _____	no _____	no _____

42. Further Description of Important Interior and Exterior Features (Continued from page 1)

remembers that the interior was designed to the exact specifications of Standard Drug, the building's first tenant and probably Oberlin's first chain store.

43. History and Significance (Continued from page 1.)