

OHIO HISTORIC INVENTORY

Ohio Historic Preservation Office
567 E. Hudson St. Columbus, Ohio 43211
614/297-2470



1. No.	2. County LOR	4. Present Name(s) Edward Jones Investment		<input type="checkbox"/> Coded
3. Location of Negatives O.H.I.O. Resource		5. Historic or Other Name(s) North: Morris Meat Market; Gerber & Haskins Meat Market; BeVier's Dry Goods. Inc. South: Shoe Repair (Rubino; Mira; Chatorian); BeVier's Dry Goods, Inc. Bunny's Flower & Gift Shop		
Roll #	Exp. #			
Front 1	2	W		
Rear 2	5	E		
6. Specific Address or Location 20 South Main Street		17. Date(s) or Period 1903	17b. Alteration Date(s)	30. Foundation Material Brick
6a. Lot, Section or VMD Number 09-00-085-112-017		18. Style or Design No academic style - vernacular	High Style <input type="checkbox"/>	31. Wall Construction Brick
7. City or Village Oberlin		18a. Style of Addition or Element(s)		32. Roof: Type Other Pitch Low Material Shingle
8. Site Plan with North Arrow		19. Architect or Engineer		33. No. Bays Front three Side
		19a. Design Sources		34. Exterior Wall Material(s) Brick
		20. Contractor or Builder		35. Plan Shape Rectangular
9. U.T.M. Reference		21. Building Type or Plan Other		36. Changes (Explain in #42) Altered
Zone	Easting	Northing		37. Window Type(s) Other
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		38. Bldg. Dims. 34 ft. X 75 ft.
10. <input type="checkbox"/> Site <input type="checkbox"/> Structure		23. Present Use Retail		39. Endangered? no Explain:
<input checked="" type="checkbox"/> Building <input type="checkbox"/> Object		24. Ownership <input type="checkbox"/> Public <input checked="" type="checkbox"/> Private		40. Chimney Placement Lateral Wall Flush
11. On National Register ? no		25. Owner's Name & Address, if known		41a. Distance from road 12.5 ft.
12. N.R. Potential ? no		26. Property Acreage .059		41b. Frontage on road 34 ft.
13. Part of Estb Hist Dist? no		27. Other Surveys in Which Included Dobson-Brown (92)		
14. Dist. Potential ? yes		28. No. of Stories 1		
15. Name of Established District (N.R. or Local)		29. Basement? Yes		
16. Thematic Association(s) Commerce		42. Further Description of Important Interior and Exterior Features This one story commercial structure has Roman brick with fine mortar joints and stone coping. The storefront area has been altered with vertical wood siding around large storefront windows.		
43. History and Significance Built in 1903, this structure is on a site where fires had destroyed two earlier buildings. The original building was the two story barn originally located behind "Oberlin Hall"; the barn was moved to this site in 1850. In 1886 the barn was destroyed by fire and replaced by a two story frame building that was destroyed by fire in 1902. This 1903 brick structure was divided into two storefronts for many years; it was converted to one storefront in 1932 when the dry goods business opened. The southern storefront was shoe repair from 1903-1932; meat markets from 1903 - 1932. (cont)		46. Prepared by		
44. Description of Environment and Outbuildings (see #52) This building is one of the many structures that make up the core of South Main's downtown commercial district. Its history indicates its importance to small town commerce.		47. Organization O.H.I.O. and H.P.C.		
45. Sources of Information Fred Maddock files at O.H.I.O. Resource Center and Oberlin College Archives; Oberlin H.P.C. files; Lorain County Courthouse tax records.		48. Date Recorded 12/8/1998		
		49. Revised by		
		50a. Date Revised		
		50b. Reviewed by		

51. Condition of Property

<input type="checkbox"/> Excellent	<input type="checkbox"/> Ruin
<input checked="" type="checkbox"/> Good/Fair	<input type="checkbox"/> Destroyed/Burned
<input type="checkbox"/> Deteriorated	Date _____

54. Farmstead Plan



52. Historic Outbuildings and Dependencies

Barn Type(s)

<input type="checkbox"/> Corn Crib or Shed	<input type="checkbox"/> Summer Kitchen	<input type="checkbox"/> Silo
<input type="checkbox"/> Smoke House	<input type="checkbox"/> Spring House	<input type="checkbox"/> Ice House
<input type="checkbox"/> Designed Landscape Features	<input type="checkbox"/> Privy	<input type="checkbox"/> Garage

53. Affiliated OAI Site Number(s) _____

OAI Completed? _____

Archaeological Feature:	Observed	Expected on Basis of Archival Research
Well	no _____	no _____
Privy	no _____	no _____
Cistern	no _____	no _____
Foundation	no _____	no _____
Structural Rubble	no _____	no _____
Formal Trash Dump	no _____	no _____
Other _____	no _____	no _____

42. Further Description of Important Interior and Exterior Features (Continued from page 1)

43. History and Significance (Continued from page 1.)