

# OHIO HISTORIC INVENTORY

Ohio Historic Preservation Office  
567 E. Hudson St. Columbus, Ohio 43211  
614/297-2470



1. No.	2. County LOR	4. Present Name(s)		<input type="checkbox"/> Coded
3. Location of Negatives O.H.I.O. Resource		5. Historic or Other Name(s) Horn House, Lemmon House		
Roll #	Exp. #			
Front	2	06		
6. Specific Address or Location 98 Union Street		17. Date(s) or Period 1910-1916	17b. Alteration Date(s)	30. Foundation Material Sandstone
6a. Lot, Section or VMD Number 0900075105077		18. Style or Design Dutch Colonial Revival	High Style <input checked="" type="checkbox"/>	31. Wall Construction Wood Frame
7. City or Village Oberlin		18a. Style of Addition or Element(s)		32. Roof: Type Gambrel Pitch Steep Material Asphalt Shingle
8. Site Plan with North Arrow		19. Architect or Engineer unknown		33. No. Bays Front 2 Side 3
		19a. Design Sources unknown		34. Exterior Wall Material(s) Wood, Shingle
		20. Contractor or Builder John H. Horn		35. Plan Shape Rectangular
9. U.T.M. Reference		21. Building Type or Plan Other House		36. Changes (Explain in #42) Unknown
Zone	Eastings	22. Original Use, if apparent Single Dwelling		37. Window Type(s) Other
<input type="checkbox"/>	<input type="checkbox"/>	23. Present Use Multiple Dwelling, Apartment House		38. Bldg. Dims. 23' x 50'
10. <input type="checkbox"/> Site <input type="checkbox"/> Structure		24. Ownership <input type="checkbox"/> Public <input checked="" type="checkbox"/> Private		39. Endangered? No Explain:
<input checked="" type="checkbox"/> Building <input type="checkbox"/> Object		25. Owner's Name & Address, if known		40. Chimney Placement Off Center Within Roof Surface
11. On National Register ? No	12. N.R. Potential ? Yes	26. Property Acreage .29		41a. Distance from road 25' approx.
13. Part of Estb Hist Dist? No	14. Dist. Potential ? Yes	27. Other Surveys in Which Included no		41b. Frontage on road 66'
15. Name of Established District (N.R. or Local)		28. No. of Stories 2		
16. Thematic Association(s) Builder/Residential		29. Basement? Full		
42. Further Description of Important Interior and Exterior Features This house has a typical Dutch Revival gambrel roof with cornice returns. The house has a porch on front, which is supported by square columns. Wood lattice covers the undercroft. The front door is on the left side of the porch. On each side of the house are three wall dormers, and there is a door into the house on the west side.				
43. History and Significance Built some time between 1910 and 1916, John H. Horn, contractor and builder, was the first listed resident. Mrs. Mariah M. Lemmon lived in the house by 1937: at first Katherine and Miriam Lemmon, two students, lived with her. By the mid-fifties, N. Florence Pope was living in the house with Mrs. Mariah Lemmon.				
44. Description of Environment and Outbuildings (see #52) A one and a half story detached garage sits behind the house, which also has a gambrel roof, and a door on the top story. A driveway on the east side of the house leads to this garage. The house is directly east of a parking lot for Oberlin College students and the Oberlin athletic fields.				
45. Sources of Information Lorain County Courthouse, Auditor Property Records, 2001. Internet. <a href="http://www.loraincounty.com/auditor/index.shtml">http://www.loraincounty.com/auditor/index.shtml</a> . Oberlin Historic Preservation Commission Files. O.H.I.O. Resource Center Files. Oberlin City Directories.				
46. Prepared by D.G. Henry, G. Baudoin, M. Franck				
47. Organization O.H.I.O. and H.P.C.				
48. Date Recorded 2/2/2002				
49. Revised by				
50a. Date Revised				
50b. Reviewed by				

51. Condition of Property

- Excellent                       Ruin  
 Good/Fair                       Destroyed/Burned  
 Deteriorated                      Date \_\_\_\_\_

54. Farmstead Plan



52. Historic Outbuildings and Dependencies

Barn Type(s)

n/a

- Corn Crib or Shed                       Summer Kitchen                       Silo  
 Smoke House                       Spring House                       Ice House  
 Designed Landscape Features                       Privy                       Garage

53. Affiliated OAI Site Number(s) \_\_\_\_\_

OAI Completed? \_\_\_\_\_

Archaeological Feature:	Observed	Expected on Basis of Archival Research
Well	<u>No</u> _____	<u>No</u> _____
Privy	<u>No</u> _____	<u>No</u> _____
Cistern	<u>No</u> _____	<u>No</u> _____
Foundation	<u>No</u> _____	<u>No</u> _____
Structural Rubble	<u>No</u> _____	<u>No</u> _____
Formal Trash Dump	<u>No</u> _____	<u>No</u> _____
Other _____	<u>No</u> _____	<u>No</u> _____

42. Further Description of Important Interior and Exterior Features (Continued from page 1)

43. History and Significance (Continued from page 1.)