

OHIO HISTORIC INVENTORY

Ohio Historic Preservation Office
567 E. Hudson St. Columbus, Ohio 43211
614/297-2470



1. No.	2. County LOR	4. Present Name(s) Weeks House	<input checked="" type="checkbox"/> Coded
3. Location of Negatives O.H.I.O. Resource		5. Historic or Other Name(s) Weeks House, McGrann House, Ives House, Wolt House, Lyman House	
Roll #	Exp. #	Facing	
Front	3	01	

6. Specific Address or Location 59 Willard Court	17. Date(s) or Period c.1910	17b. Alteration Date(s)	30. Foundation Material Sandstone
6a. Lot, Section or VMD Number 0900086101028	18. Style or Design No academic style - vernacular	High Style <input type="checkbox"/>	31. Wall Construction Wood Frame
7. City or Village Oberlin	18a. Style of Addition or Element(s)	Elements <input type="checkbox"/>	32. Roof: Type Gable Pitch Steep Material Asphalt Shingle
8. Site Plan with North Arrow	19. Architect or Engineer unknown		33. No. Bays Front 2 Side 2
	19a. Design Sources unknown		34. Exterior Wall Material(s) Wood, Narrow Horizontal Siding
	20. Contractor or Builder unknown		35. Plan Shape Square
9. U.T.M. Reference	21. Building Type or Plan Four-over-Four		36. Changes (Explain in #42) Unknown
Zone	22. Original Use, if apparent Single Dwelling		37. Window Type(s) 1 over 1
Easting	23. Present Use Single Dwelling		38. Bldg. Dims. 23' x 36'
Northing	24. Ownership <input type="checkbox"/> Public <input checked="" type="checkbox"/> Private		39. Endangered? No Explain:
	25. Owner's Name & Address, if known		40. Chimney Placement Center
10. <input type="checkbox"/> Site <input type="checkbox"/> Structure	26. Property Acreage .10		41a. Distance from road 15' approx.
<input type="checkbox"/> Building <input type="checkbox"/> Object	27. Other Surveys in Which Included no		41b. Frontage on road 45'
11. On National Register? No	28. No. of Stories 2 and 1/2		
12. N.R. Potential? Yes	29. Basement? Full		
13. Part of Estb Hist Dist? No			
14. Dist. Potential? Yes			
15. Name of Established District (N.R. or Local)			
16. Thematic Association(s) Commercial			

42. Further Description of Important Interior and Exterior Features
This square house has a simple design. On the front is an enclosed porch with a hip roof and round columns. The home has simple rectangular windows, a beltcourse, and cornice returns. The windows on the front of the house have hoods over them. There is a door on the north side of the house. It is very similar to its neighbor.

43. History and Significance
This house was built some time between 1910 and 1916. Its first resident was Charles Weeks in 1916. In 1929, Dr. James A. McGrann lived in the house. Mrs. Harriet Ives, a housekeeper, occupied the house through most of the 1930s. Edward Woldt lived there in 1942, and in the 1950s, the house was occupied by David L. Lyman of Lyman Radio and Television at 61 South Main St. and his wife Helen. It is now used as the office for Peace Community Church.

44. Description of Environment and Outbuildings (see #52)
This house sits on an alleyway that leads to the back of the Allen Memorial Art Museum and the Oberlin Inn. There is a two-sided shed on the north side of the house approached by a paved driveway. There are several trees in the small yard.

45. Sources of Information
Lorain County Courthouse, Auditor Property Records, 2001. Internet.
<http://www.loraincounty.com/auditor/index.shtml>. Oberlin Historic Preservation Commission Files. O.H.I.O. Resource Center Files. Oberlin City Directories.

46. Prepared by D.G. Henry, G. Baudoin, M. Franck
47. Organization O.H.I.O. and H.P.C.
48. Date Recorded 1/25/2002
49. Revised by
50a. Date Revised
50b. Reviewed by

51. Condition of Property

- Excellent Ruin
 Good/Fair Destroyed/Burned
 Deteriorated Date _____

54. Farmstead Plan



52. Historic Outbuildings and Dependencies

Barn Type(s)

n/a

- Corn Crib or Shed Summer Kitchen Silo
 Smoke House Spring House Ice House
 Designed Landscape Features Privy Garage

53. Affiliated OAI Site Number(s) _____

OAI Completed? _____

Archaeological Feature:	Observed	Expected on Basis of Archival Research
Well	No _____	No _____
Privy	No _____	No _____
Cistern	No _____	No _____
Foundation	No _____	No _____
Structural Rubble	No _____	No _____
Formal Trash Dump	No _____	No _____
Other _____	No _____	No _____

42. Further Description of Important Interior and Exterior Features (Continued from page 1)

43. History and Significance (Continued from page 1.)